



BMW 3: 1GDZ091			
Vinnnumber:	WBA3Y11070D375657	Versionname:	3 GRAN TURISMO 318dA
First Registrationdate:	13/01/2014	Fiscalpower:	136PK Aut.
Expertise Mileage:	183768	Power Kw:	100
Bodytype:		Body color:	Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4123
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options	
Windows electric F	Central consol F
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Seats F heated	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	225/55/17/97 Y LightMetal			
Summer tyres:	Fr.L.	Bridgestone: 6 mm	Fr.R.	Bridgestone: 6 mm
	Re.L.	Goodyear: 4 mm	Re.R.	Goodyear: 4 mm

Assistance equipment	
Runflat	Yes
Total cost ex VAT	2304,00
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00
--	--------------



Tailgate, Scratch(es), LI - Repair and paint (complete) 362,02



Door F L, Scratch(es), LI - Repair and paint (complete) 382,02



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete) 254,16



Bonnet, Stone chip(s), Acceptable 0,00

No pictures to display

Wing R R, Bump(s), PDR - Knock out without painting 63,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Maintenance book, Missing, E - Replace 0,00

No pictures to display

Front bumper, Damaged, Le - Replace and paint 862,80



Rearview mirror housing R, Scratch(es), Acceptable 0,00

No pictures to display