


**LAND ROVER Evoque: 1FDU746**

|                         |                          |              |                            |
|-------------------------|--------------------------|--------------|----------------------------|
| Vinnnumber:             | <b>SALVB2DC4DH791097</b> | Versionname: | <b>EVOQUE eD4 2WD Pure</b> |
| First Registrationdate: | <b>3/06/2013</b>         | Fiscalpower: | <b>150PK</b>               |
| Expertise Mileage:      | <b>120187</b>            | Power Kw:    | <b>110</b>                 |
| Bodytype:               |                          | Body color:  | <b>Black</b>               |
| Gearbox:                | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>             |
| Transmission:           | <b>Front</b>             | Rims summer: | <b>Aluminium</b>           |
| Fueltype:               | <b>Diesel</b>            | Oil level:   | <b>OK</b>                  |
| Maintenance:            | <b>OK</b>                | Parking lot: | <b>3732</b>                |
| Battery functioning:    | <b>Yes</b>               |              |                            |
| Number of doors:        | <b>5</b>                 |              |                            |
| Number of seats:        | <b>5</b>                 |              |                            |
| Number head rests:      | <b>4</b>                 |              |                            |
| Rims summer:            | <b>Aluminium</b>         |              |                            |
| Category:               | <b>Passenger Car</b>     |              |                            |
| Oil level:              | <b>OK</b>                |              |                            |

**Options**

|                                |                              |                       |
|--------------------------------|------------------------------|-----------------------|
| Radio CD                       |                              | Seats electric F L    |
| GPS storage                    |                              | Seats electric F R    |
| GPS storage                    | <b>HD</b>                    | Panoramic roof        |
| Windows electric F             |                              | Central consol F      |
| Windows electric R             |                              | Luggage cover         |
| Cruise Control                 |                              | Front parking sensors |
| Steering wheel multifunctional |                              | Rear parking sensors  |
| Seats F heated                 |                              |                       |
| Type of headlighting           | <b>Headlighting Xenon</b>    |                       |
| Type of GPS                    | <b>GPS big screen color</b>  |                       |
| Type of Lining                 | <b>Lining leather</b>        |                       |
| Type of climate control        | <b>Autom climate control</b> |                       |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                                   |                         |       |                         |
|---------------|-----------------------------------|-------------------------|-------|-------------------------|
|               | <b>235/55/19/105 V LightMetal</b> |                         |       |                         |
| Winter tyres: | Fr.L.                             | <b>Goodyear: 5,5 mm</b> | Fr.R. | <b>Goodyear: 5,5 mm</b> |
|               | Re.L.                             | <b>Goodyear: 5,5 mm</b> | Re.R. | <b>Goodyear: 5,5 mm</b> |

**Assistance equipment**

|            |            |            |            |
|------------|------------|------------|------------|
| Repair kit | <b>Yes</b> | Compressor | <b>Yes</b> |
|------------|------------|------------|------------|

|  |        |
|--|--------|
| Total cost ex VAT  | 236,56 |
| Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete) | 115,56 |



|   |        |
|---|--------|
| Door R L, Bump(s), PDR - Knock out without painting | 111,00 |
|---|--------|



|                                       |       |
|---------------------------------------|-------|
| Partition net, Strained , E - Replace | 10,00 |
|---------------------------------------|-------|



|   |      |
|---|------|
| Ignition key, Not functioning (well), Repair/replace (lump sum) | 0,00 |
|---|------|

