



BMW X3: 1EAK184			
Vinnnumber:	<b>WBAWY31060L618342</b>	Versionname:	<b>X3 xDrive20 163PK</b>
First Registrationdate:	<b>3/10/2012</b>	Fiscalpower:	
Expertise Mileage:	<b>185546</b>	Power Kw:	<b>120</b>
Bodytype:	<b>SUV</b>	Body color:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>4 Weel</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3125</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

Options			
Radio CD		Central consol F	
GPS storage	<b>HD</b>	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	<b>Tow bar removable</b>
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining leather</b>		
Type of climate control	<b>Autom climate control</b>		

Limited Technical Inspection			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

Degree of wear				
	<b>225/60/17/99 V LightMetal</b>			
Summer tyres:	Fr.L.	<b>Pirelli: 3 mm</b>	Fr.R.	<b>Pirelli: 3 mm</b>
	Re.L.	<b>Pirelli: 3 mm</b>	Re.R.	<b>Pirelli: 3 mm</b>

Assistance equipment	
Runflat	<b>Yes</b>
Total cost ex VAT	<b>387,12</b>
Roof pillar L, Chemical polution, LI - Repair and paint (complete)	<b>0,00</b>



Alloy rim F R, Scratch(es), Acceptable	<b>0,00</b>
<i>No pictures to display</i>	
Ceiling, Scratch(es), Acceptable	<b>0,00</b>
<i>No pictures to display</i>	
Rear spoiler, Chemical polution, LI - Repair and paint (complete)	<b>115,56</b>



Foglight R, Broken, E - Replace	156,00
---------------------------------	--------



Headlight R, Scratch(es), Acceptable	0,00
--------------------------------------	------

*No pictures to display*

Dashboard, Scratch(es), Acceptable	0,00
------------------------------------	------

*No pictures to display*

Bumper trim R, Scratch(es), Acceptable	0,00
--	------

*No pictures to display*

Rocker panel inner R L, Scratch(es), Acceptable	0,00
---	------

*No pictures to display*

Bumper R, Scratch(es), LI - Repair and paint (complete)	0,00
---	------



Headlight L, Scratch(es), Acceptable	0,00
--------------------------------------	------

*No pictures to display*


Alloy rim R R, Scratch(es), Acceptable	0,00
--	------

*No pictures to display*


Tailgate, Scratch(es), Acceptable	0,00
-----------------------------------	------

*No pictures to display*

Bonnet, Chemical polution, LI - Repair and paint (complete)	0,00
---	------



Roof, Chemical polution, LI - Repair and paint (complete)	0,00
---	------



Wing R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

*No pictures to display*

Tailgate, Scratch(es), It - Spot repair	115,56
---	--------

