


FORD Galaxy: 1FCO219

Vinnumber:	WF0MXXGBWMDP14006	Versionname:	Econetic Trend St&St DPF
First Registrationdate:	24/05/2013	Fiscalpower:	115PK
Expertise Mileage:	144506	Power Kw:	85
Bodytype:		Body color:	Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4829
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	No		

Options

Radio CD		Seats electric F L
GPS storage		Central consol F
GPS storage	SD	Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/60/16/99 H LightMetal			
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	936,65
-------------------	--------

Door F R, Bump(s) and scratch(es), Acceptable	0,00
---	------

No pictures to display

Door R L, Bump(s) and scratch(es), Acceptable	0,00
---	------

No pictures to display

Bonnet, Stone chip(s), Acceptable	0,00
-----------------------------------	------

No pictures to display

Wing R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Windscreen, Repaired, P - Check	0,00
---------------------------------	------



Wing F L, Scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Scratch(es), Acceptable 0,00

No pictures to display


Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Tailgate, Stain, Acceptable 0,00

No pictures to display

Door F L, Bump(s), LI - Repair and paint (complete) 366,35



Sill outer L, Bump(s) and scratch(es), LI - Repair and paint (complete) 358,50



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display