



CITRO?N C4 Picasso: 1FAY538

Vinnnumber:	VF7UA9HR8DJ631268	Versionname:	GR.C4 PICASSO
First Registrationdate:	13/05/2013	7pl.Excl.BMP FAP 112PK	Aut
Expertise Mileage:	150072	Fiscalpower:	
Bodytype:		Power Kw:	82
Gearbox:	Automatic	Body color	Brown
Transmission:	Front	Paint type	Metalic
Fueltype:	Diesel	Rims summer	Aluminium
Maintenance	OK	Oil level	OK
Battery functioning	Yes	Parking lot	4612
Number of doors	5		
Number of seats	7		
Number head rests	7		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options

Radio CD		Panoramic roof	
GPS storage	HD	Central consol F	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	Tow bar fixed
Cruise Control			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/55/16/93 V LightMetal			
Summer tyres:	Fr.L.	Uniroyal: 8 mm	Fr.R.	Uniroyal: 8 mm
	Re.L.	Goodyear: 4 mm	Re.R.	Goodyear: 4 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	1982,31
Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80



Wing F R, Bump(s) and scratch(es), LI - Repair and paint (complete)	268,18
---	--------



Wing R L, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Rearview mirror housing R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Windscreen, Stone chip(s), Windscreen repair	0,00



Alloy rim F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door R L, Bump(s) and scratch(es), LI - Repair and paint (complete)	366,35



Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------




Tailgate, Scratch(es), LI - Repair and paint (complete)	301,68
---	--------



Sill outer R, Bump(s) and scratch(es), LI - Repair and paint (complete)	382,50
---	--------





Door R R, Scratch(es), LI - Repair and paint (complete) 0,00



Luggage space cover, Missing, E - Replace 240,00



Alloy rim R L, Scratch(es), Acceptable 0,00

No pictures to display