


LANCIA Delta: 1FTN087

Vinnumber:	ZLA8440001123558	Versionname:	DELTA Platinum SelecTronic 115PK Aut.
First Registrationdate:	21/10/2013	Fiscalpower:	
Expertise Mileage:	159313	Power Kw:	85
Bodytype:		Body color:	Brown
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2425
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	4		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Sun Roof electric
GPS storage	SD	Central consol F
GPS storage		Luggage cover
Windows electric F		Front parking sensors
Windows electric R		Rear parking sensors
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/45/17/91 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	910,15
-------------------	---------------

Roof, Scratch(es), Acceptable	0,00
-------------------------------	-------------



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
--------------------------------------------------------------	--------------



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Trunk lid covering R, Scratch(es), Acceptable 0,00

No pictures to display

Door F L, Bump(s), Acceptable 0,00



Roof pillar R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Door R L, Bump(s), LI - Repair and paint (complete) 318,35



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Door F R, Bad repair, Acceptable 0,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Rearview mirror housing R, Scratch(es), Acceptable 0,00

No pictures to display