


FORD Transit 350L: 817BMM

Vinnnumber:	WF0XXXTFXAL57634	Versionname:	TRANSIT 350L B/F LWB 4x4 Silv.DPF 140PK
First Registrationdate:	7/04/2010	Fiscalpower:	
Expertise Mileage:	244045	Power Kw:	103
Bodytype:		Body color	White
Gearbox:	MAN 6 VIT	Paint type	Opaque
Transmission:	4 Weel	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	LCV15
Battery functioning	Yes		
Number of doors	5		
Number of seats	3		
Number head rests	3		
Rims summer	Steel		
Category	Light Commercial Vehicle		
Oil level	OK		

Options

Radio CD	Central consol F
GPS storage	
GPS storage	SD
Windows electric F	
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/75/16/114 R Steel			
Summer tyres:	Fr.L.	Dunlop: 8,5 mm	Fr.R.	Dunlop: 8,5 mm
	Re.L.	Michelin: 7 mm	Re.R.	Michelin: 7 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	2040,69
Ignition key, Missing, E - Replace	150,00
<i>No pictures to display</i>	
Rearlight R , Damaged, E - Replace	91,50



Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete)	423,15
---	--------



Trunk door R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 185,00



Certificate Of Conformity, Missing, E - Replace 150,00

No pictures to display

Bonnet, Scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 231,15



Central pillar R, Bump(s) and scratch(es), LI - Repair and paint (complete) 414,49



Windscreen, Damaged, E - Replace 395,40

