


**FORD FOCUS CLIPPER: 1RBE286**

Vinnnumber:	<b>WF06XXGCC6GA23394</b>	Versionname:	<b>1.0I ECOBOOST 92KW S/S BUSINESS CLASS+</b>
First Registrationdate:	<b>3/11/2016</b>	Fiscalpower:	
Expertise Mileage:	<b>52379</b>	Power Kw:	<b>92</b>
Bodytype:	<b>Bus</b>	Body color:	<b>Silver</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Petrol</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>2208</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F
GPS storage		Luggage cover
GPS storage	<b>HD</b>	Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining fabrics</b>	
Type of climate control	<b>Autom climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>205/55/16/94 V LightMetal</b>			
Summer tyres:	Fr.L.	<b>Fulda: 5 mm</b>	Fr.R.	<b>Fulda: 5 mm</b>
	Re.L.	<b>Fulda: 7 mm</b>	Re.R.	<b>Fulda: 7 mm</b>

**Assistance equipment**

Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-----------------------	------------	------	------------

 Total cost ex VAT 232,44

 Door R L, Bump(s), PDR - Knock out without painting 63,00

 Rocker panel inner R L, Scratch(es), Acceptable 0,00

No pictures to display

 Windscreen, Stone chip(s), Windscreen repair 58,80



Bumper R, Scratch(es), Smart repair 110,64



Wing R R, Scratch(es), Acceptable 0,00

No pictures to display