


**CITROEN GRAND C4 PICASSO: 1KBE069**

Vinnnumber:	<b>VF73AAHRMFJ585042</b>	Versionname:	<b>2.0 BLUEHDI 150 MAN6 EXCLUSIVE</b>
First Registrationdate:	<b>24/03/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>149761</b>	Power Kw:	<b>110</b>
Bodytype:		Body color:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>NOT OK</b>	Parking lot:	<b>2720</b>
Maintenance:	<b>OLIE VERVERSEN</b>		
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>7</b>		
Number head rests:	<b>7</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

GPS storage		Central consol F	
GPS storage	<b>HD</b>	Luggage cover	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	<b>Tow bar fixed</b>
Steering wheel multifunctional			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining semi-leather</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>205/55/17/95 V LightMetal</b>			
Summer tyres:	Fr.L.	<b>Michelin: 4 mm</b>	Fr.R.	<b>Michelin: 4 mm</b>
	Re.L.	<b>Michelin: 5 mm</b>	Re.R.	<b>Michelin: 5 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	<b>2109,08</b>
Wing F R, Scratch(es), Acceptable	<b>0,00</b>
<i>No pictures to display</i>	
Bonnet, Scratch(es), Acceptable	<b>0,00</b>
<i>No pictures to display</i>	
Wing R R, Scratch(es), Acceptable	<b>0,00</b>
<i>No pictures to display</i>	
Alloy rim F R polished, Rust, LI - Repair and paint (complete)	<b>95,00</b>



Door panel R L, Scratch(es), Smart repair 110,64



Alloy rim F L polished, Rust, LI - Repair and paint (complete) 95,00



Front bumper, Scratch(es), Acceptable 0,00

No pictures to display

Door frame F R, Bump(s) and scratch(es), It - Spot repair 115,56



Tailgate, Scratch(es), LI - Repair and paint (complete) 301,68



Maintenance, Maintenance, Execute 0,00



Rearview mirror housing R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R R polished, Rust, LI - Repair and paint (complete) 95,00



Windscreen, Broken, E - Replace 487,20



Alloy rim R L polished, Rust, LI - Repair and paint (complete) 95,00



Bumper R, Damaged, Le - Replace and paint 651,00



Door R R, Bump(s), PDR - Knock out without painting 63,00



Wing R L, Scratch(es), Acceptable 0,00

No pictures to display