



**FORD Focus: 1GNU615**

Vinnumber:	<b>WF0LXXGCBLES16577</b>	Versionname:	<b>FOCUS CLIP. EConetic T.Trend 115PK</b>
First Registrationdate:	<b>20/03/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>122837</b>	Power Kw:	<b>85</b>
Bodytype:		Body color	<b>Brown</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level	<b>OK</b>
Maintenance	<b>NOT OK</b>	Parking lot	<b>3714</b>
Battery functioning	<b>Yes</b>		
Number of doors	<b>5</b>		
Number of seats	<b>5</b>		
Number head rests	<b>5</b>		
Rims summer	<b>Aluminium</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		
Registration Certificate Car (BE)	<b>Yes</b>		

**Options**

Radio CD		Central consol F	
GPS storage	<b>SD</b>	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	<b>Tow bar fixed</b>
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Manual climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>215/55/16/93 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Goodyear: 8 mm</b>	Fr.R.	<b>Goodyear: 8 mm</b>
	Re.L.	<b>Uniroyal: 6 mm</b>	Re.R.	<b>Uniroyal: 6 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	<b>1780,30</b>
-------------------	----------------

Trunk lid covering R, Scratch(es), Smart repair	<b>110,64</b>
---	---------------



Alloy rim R L, Scratch(es), Acceptable	<b>0,00</b>
--	-------------

No pictures to display

Wing F L, Scratch(es), LI - Repair and paint (complete) 220,18



Front bumper, Bump(s) and scratch(es), LI - Repair and paint (complete) 259,80



Alloy rim F L, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Bump(s) and scratch(es), Le - Replace and paint 651,00



Tailgate, Bump(s) and scratch(es), LI - Repair and paint (complete) 325,68



Maintenance, Maintenance, Execute 0,00

No pictures to display

Ignition key, Missing, E - Replace 150,00



Roof pillar L, Bump(s), PDR - Knock out without painting 63,00

