



BMW i3: 1HZV997

| | | | |
|-----------------------------------|--------------------------|--------------|--|
| Vinnumber: | WBY1Z41040VZ73013 | Versionname: | i3 Advanced Range Extender 170PK Aut. |
| First Registrationdate: | 12/11/2014 | Fiscalpower: | |
| Expertise Mileage: | 103609 | Power Kw: | 75 |
| Bodytype: | | Body color | Grey |
| Gearbox: | Automatic | Paint type | Metalic |
| Transmission: | Back | Rims summer | Aluminium |
| Fueltype: | Hybrid Petrol | Oil level | OK |
| Maintenance | 9:1018 | Parking lot | 3408 |
| Maintenance | OK | | |
| Battery functioning | Yes | | |
| Number of doors | 5 | | |
| Number of seats | 4 | | |
| Number head rests | 2 | | |
| Rims summer | Aluminium | | |
| Category | Passenger Car | | |
| Oil level | OK | | |
| Registration Certificate Car (BE) | Yes | | |

Options

| | | |
|--------------------------------|------------------------------|----------------------|
| GPS storage | HD | Central consol F |
| GPS storage | | Luggage cover |
| Windows electric F | | Rear parking sensors |
| Cruise Control | | |
| Steering wheel multifunctional | | |
| Radio multimedia | | |
| Type of headlighting | Headlighting LED | |
| Type of GPS | GPS big screen color | |
| Type of Lining | Lining fabrics | |
| Type of climate control | Autom climate control | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|----------------------------------|--------------------------|-------|--------------------------|
| | 155/70/19/84 Q LightMetal | | | |
| Summer tyres: | Fr.L. | Bridgestone: 6 mm | Fr.R. | Bridgestone: 6 mm |
| | Re.L. | Bridgestone: 5 mm | Re.R. | Bridgestone: 5 mm |

Assistance equipment

| | | | |
|------------------------------------|----------|---------|------------|
| Number of charging cables (normal) | 1 | Runflat | Yes |
|------------------------------------|----------|---------|------------|

| | |
|-------------------|-------------|
| Total cost ex VAT | 0,00 |
|-------------------|-------------|

| | |
|---------------------------------|-------------|
| Door seal F L, Worn, Acceptable | 0,00 |
|---------------------------------|-------------|



| | |
|---|-------------|
| Bumper R, Unclapsed, N - Mount/Dismount | 0,00 |
|---|-------------|

