



RENAULT Grand Scenic: 1EWM219

Vinnnumber:	VF1JZ14B648777762	Versionname:	GR.SCENIC Energ.Privilege 7pl.FAP 110PK
First Registrationdate:	8/04/2013	Fiscalpower:	
Expertise Mileage:	127860	Power Kw:	81
Bodytype:	MPV	Body color:	Red
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4622
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Seats electric F L	
Windows electric F	Central consol F	
Windows electric R	Luggage cover	
Cruise Control	Front parking sensors	
Steering wheel multifunctional	Rear parking sensors	
Seats F heated	Type of Tow bar	Tow bar fixed
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather and alcantara	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/17/95 V LightMetal			
Summer tyres:	Fr.L.	Kleber: 4 mm	Fr.R.	Kleber: 4 mm
	Re.L.	Kleber: 5 mm	Re.R.	Kleber: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT 1403,30

Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete) 308,20



Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete) 211,80





Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim R L, Scratch(es), Acceptable 0,00

No pictures to display

Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Roof, Chemical polution, LI - Repair and paint (complete) 481,50

