


**OPEL Zafira: 1GDK059**

Vinnumber:	<b>WOLPE9E37E2043235</b>	Versionname:	<b>ZAFIRA TOURER ecoFL.Cosmo S/S 136PK</b>
First Registrationdate:	<b>8/01/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>147940</b>	Power Kw:	<b>100</b>
Bodytype:		Body color:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OH NU</b>	Parking lot:	<b>2328</b>
Maintenance:	<b>NOT OK</b>		
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Seats electric F L
GPS storage		Central consol F
GPS storage	<b>SD</b>	Luggage cover
Windows electric F		Front parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Radio multimedia		
Type of headlighting:	<b>Headlighting Halogen</b>	
Type of GPS:	<b>GPS big screen color</b>	
Type of Lining:	<b>Lining leather</b>	
Type of climate control:	<b>Manual climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>225/50/17/98 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Semperit: 5 mm</b>	Fr.R.	<b>Semperit: 5 mm</b>
	Re.L.	<b>Michelin: 7 mm</b>	Re.R.	<b>Michelin: 7 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	<b>815,80</b>
-------------------	---------------

Windscreen, Scratch(es), Acceptable	<b>0,00</b>
-------------------------------------	-------------



Bumper R, Scratch(es), LI - Repair and paint (complete)	<b>211,80</b>
---	---------------



Door R R, Bump(s), Acceptable 0,00



Ceiling, Stain, Acceptable 0,00



Door seal R, Worn, Acceptable 0,00



Spoiler F L, Scratch(es), E - Replace 42,00



Spoiler F R, Missing, E - Replace 42,00



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Maintenance, Maintenance, Execute 0,00



Wing R L, Scratch(es), LI - Repair and paint (complete) 308,20



Tailgate, Bump(s), Acceptable 0,00

