



**PEUGEOT PARTNER: 1JXP949**

Vinnnumber:	<b>VF37A9HL0FJ557050</b>	Versionname:	<b>1.6 HDI 120 L1H1 84KW CONFORT</b>
First Registrationdate:	<b>13/03/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>136853</b>	Power Kw:	<b>84</b>
Bodytype:	<b>Transporter</b>	Body color:	<b>White</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Opaque</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>4230</b>
Number of doors:	<b>4</b>		
Number of seats:	<b>2</b>		
Number head rests:	<b>2</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Light Commercial Vehicle</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Rear parking sensors
Windows electric F		
Cruise Control		
Radio multimedia		
Type of headlighting:	<b>Headlighting Halogen</b>	
Type of GPS:	<b>GPS big screen color</b>	
Type of Lining:	<b>Lining fabrics</b>	
Type of climate control:	<b>Manual climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>195/65/15/91 H Steel</b>			
Summer tyres:	Fr.L.	<b>Goodyear: 3 mm</b>	Fr.R.	<b>Goodyear: 3 mm</b>
	Re.L.	<b>Goodyear: 4 mm</b>	Re.R.	<b>Goodyear: 4 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------

Total cost ex VAT	<b>461,82</b>
-------------------	---------------

Sill outer L, Scratch(es), Acceptable	<b>0,00</b>
---------------------------------------	-------------






Wheel cover F R, Scratch(es), E - Replace	<b>22,50</b>
---	--------------

No pictures to display

Seat cover F L, Hole, Smart repair	<b>64,32</b>
------------------------------------	--------------



Bumper R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Rearview mirror housing R, Broken, E - Replace	84,00
	
Sidewall RL (LCV), Rust, Acceptable	0,00
<i>No pictures to display</i>	
Rear floor , Damaged, I - Repair	228,00
	
Door F L, Bump(s), PDR - Knock out without painting	63,00
	
Bodywork, Not original part, Acceptable	0,00
<i>No pictures to display</i>	