



**OPEL Insignia: 1FEY449**

Vinnumber:	<b>W0LGT8EM7D1090603</b>	Versionname:	<b>INSIGNIA BRE ecofl.Cosmo S/S DPF 160PK</b>
First Registrationdate:	<b>11/06/2013</b>	Fiscalpower:	<b>118</b>
Expertise Mileage:	<b>88469</b>	Power Kw:	<b>118</b>
Bodytype:	<b>Break</b>	Body color:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>4810</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD		Seats electric F L	
GPS storage	<b>SD</b>	Seats F L ventilated	
GPS storage		Seats F R ventilated	
Windows electric F		Central consol F	
Windows electric R		Luggage cover	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Seats F heated		Type of Tow bar	<b>Tow bar fixed</b>
Type of headlighting	<b>Headlighting Xenon</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining leather</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>225/55/17/97 W LightMetal</b>			
Summer tyres:	Fr.L.	<b>Michelin: 3 mm</b>	Fr.R.	<b>Michelin: 3 mm</b>
	Re.L.	<b>Michelin: 3 mm</b>	Re.R.	<b>Michelin: 3 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------







Total cost ex VAT 1526,13

Front bumper, Bump(s) and scratch(es), LI - Repair and paint (complete) 259,80



Door panel R R, Tear, E - Replace

114,00

	Wing F L, Scratch(es), LI - Repair and paint (complete)	220,18
	Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
	Alloy rim F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>		
Wing R L, Scratch(es), Acceptable		
<i>No pictures to display</i>		
Sunblind R, Incomplete, E - Replace		
150,00		
	Bodywork, Dirty, Cleaning	0,00
<i>No pictures to display</i>		
Door R L, Scratch(es), Acceptable		
<i>No pictures to display</i>		
Floor covering F L, Tear, E - Replace		
252,00		
	Door F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>		
Door F R, Scratch(es), LI - Repair and paint (complete)		
318,35		
	Wing F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>		
Alloy rim F L, Scratch(es), Acceptable		
<i>No pictures to display</i>		
Door R R, Scratch(es), Acceptable		
0,00		
<i>No pictures to display</i>		