



OPEL Insignia: 1GRP436

Vinnnumber:	WOLGT8ER6E1096096	Versionname:	INSIGNIA BRE ecoFLEX Cosmo 120PK
First Registrationdate:	9/04/2014	Fiscalpower:	
Expertise Mileage:	133626	Power Kw:	88
Bodytype:		Body color:	Silver
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3309
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

GPS storage		Central consol F
GPS storage	HD	Luggage cover
Windows electric F		Front parking sensors
Windows electric R		Rear parking sensors
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Type of headlighting	Headlighting Xenon	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	
Adaptive cruise control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/5/17/101 V LightMetal			
Winter tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Michelin: 7 mm	Re.R.	Michelin: 7 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	1168,01
-------------------	----------------

Tailgate, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Sill outer R, Damaged, LI - Repair and paint (complete)	310,50
---	---------------





Door R L, Scratch(es), LI - Repair and paint (complete) 318,35



Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete) 115,56



Front bumper, Bump(s) and scratch(es), LI - Repair and paint (complete) 211,80



Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete) 211,80



Rearview mirror housing L, Scratch(es), Acceptable 0,00

No pictures to display