



RENAULT Megane: 1FVB467			
Vinnnumber:	<b>VF1BZ1A0749472958</b>	Versionname:	<b>MEGANE BER Authentique 90PK</b>
First Registrationdate:	<b>4/11/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>66495</b>	Power Kw:	<b>66</b>
Bodytype:		Body color:	<b>Light Grey</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3729</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

Options	
Radio CD	Luggage cover
Windows electric F	
Radio multimedia	
Type of headlighting:	<b>Headlighting Halogen</b>
Type of Lining:	<b>Lining fabrics</b>
Type of climate control:	<b>Manual climate control</b>

Limited Technical Inspection			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>NOT OK</b>
		Wiperblades	<b>OK</b>

Degree of wear				
Winter tyres:	<b>195/65/15/91 T Steel</b>			
	Fr.L.	<b>Michelin: 6 mm</b>	Fr.R.	<b>Michelin: 6 mm</b>
	Re.L.	<b>Michelin: 7 mm</b>	Re.R.	<b>Michelin: 7 mm</b>

Assistance equipment			
Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>

Total cost ex VAT	3452,46
Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete)	318,35



Bumper R, Damaged, Le - Replace and paint	651,00
---	--------



Floor covering F L, Damaged, E - Replace 252,00




Backrest cover F L, Damaged, E - Replace 360,00




Interior, Dirty, Cleaning 50,00



Door F R, Scratch(es), LI - Repair and paint (complete) 318,35




Door F R, Scratch(es), LI - Repair and paint (complete) 318,35



Bonnet, Bump(s), LI - Repair and paint (complete) 338,08





Luggage space cover, Missing, E - Replace 24,00



Wheel cover F R, Scratch(es), E - Replace 30,00



Wheel cover F L, Scratch(es), E - Replace 30,00



Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 308,20



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Sill outer R, Bump(s) and scratch(es), LI - Repair and paint (complete) 310,50



Interior, Worn, Acceptable 0,00



Wheel cover R R, Scratch(es), E - Replace 30,00



Wing F R, Scratch(es), LI - Repair and paint (complete)

220,18

