


PEUGEOT 508: 1FGK448

| | | | |
|-------------------------|--------------------------|--------------|----------------------------|
| Vinnnumber: | VF38E9HL0DL024768 | Versionname: | 508 SW Active 115PK |
| First Registrationdate: | 21/06/2013 | Fiscalpower: | |
| Expertise Mileage: | 73979 | Power Kw: | 84 |
| Bodytype: | Break | Body color: | Light Brown |
| Gearbox: | MAN 5 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 3201 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |

Options

| | | |
|--------------------------------|------------------------------|-----------------------|
| Radio CD | | Seats electric F L |
| GPS storage | HD | Seats electric F R |
| GPS storage | | Panoramic roof |
| Windows electric F | | Central consol F |
| Windows electric R | | Luggage cover |
| Cruise Control | | Front parking sensors |
| Steering wheel multifunctional | | |
| Type of headlighting | Headlighting Xenon | |
| Type of GPS | GPS big screen color | |
| Type of Lining | Lining semi-leather | |
| Type of climate control | Autom climate control | |
| Head-up Display | | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|----------------------------------|-----------------------|-------|-----------------------|
| | 215/60/16/95 H LightMetal | | | |
| Summer tyres: | Fr.L. | Michelin: 5 mm | Fr.R. | Michelin: 5 mm |
| | Re.L. | Michelin: 7 mm | Re.R. | Michelin: 7 mm |

Assistance equipment

| | | | |
|---|------------|------|-------------|
| Spare wheel | Yes | Jack | Yes |
| Total cost ex VAT | | | 0,00 |
| Wing R L, Bump(s), Acceptable | | | 0,00 |
| <i>No pictures to display</i> | | | |
| Internal Boot Lining R, Scratch(es), Acceptable | | | 0,00 |
| <i>No pictures to display</i> | | | |
| Wing R R, Bump(s), Acceptable | | | 0,00 |
| <i>No pictures to display</i> | | | |
| Wing R L 3P, Bump(s), Acceptable | | | 0,00 |
| <i>No pictures to display</i> | | | |
| Alloy rim F L, Scratch(es), Acceptable | | | 0,00 |
| <i>No pictures to display</i> | | | |
| Door F R, Bump(s), Acceptable | | | 0,00 |
| <i>No pictures to display</i> | | | |
| Alloy rim F R, Scratch(es), Acceptable | | | 0,00 |
| <i>No pictures to display</i> | | | |

| | |
|---|------|
| Wing F L, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Door R L, Bump(s), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Internal Boot Lining L, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Trunk lid covering R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Bumper R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Roof, Bump(s), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Outer door handle F L, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |