



RENAULT Clio: 1GRP445			
Vinnnumber:	VF17R040H50462595	Versionname:	CLIO IV BRE Expression
First Registrationdate:	9/04/2014	Fiscalpower:	75PK
Expertise Mileage:	69552	Power Kw:	55
Bodytype:	Break	Body color:	Grey
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4233
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options	
Windows electric F	Luggage cover
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting:	Headlighting Halogen
Type of GPS:	GPS big screen color
Type of Lining:	Lining fabrics
Type of climate control:	Manual climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	185/65/15/88 T Steel			
Summer tyres:	Fr.L.	Bridgestone: 4 mm	Fr.R.	Bridgestone: 4 mm
	Re.L.	Bridgestone: 5 mm	Re.R.	Bridgestone: 5 mm

Assistance equipment			
Spare wheel	Yes	Jack	Yes

Total cost ex VAT	1184,02
Wheel cover F L, Damaged, E - Replace	24,00



Bumper R, Scratch(es), Smart repair	110,64
-------------------------------------	---------------



Wing F R, Scratch(es), LI - Repair and paint (complete)	176,14
---	---------------



Front bumper, Scratch(es), LI - Repair and paint (complete) 169,44



Bodywork, Not original part, Acceptable 0,00

No pictures to display

Wing R R, Scratch(es), LI - Repair and paint (complete) 246,56



Wheel cover R R, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Scratch(es), LI - Repair and paint (complete) 254,68



Door F L, Bump(s), Acceptable 0,00

No pictures to display

Door F R, Bump(s), PDR - Knock out without painting 63,00



Bumper corner R L, Scratch(es), It - Spot repair 115,56



Wheel cover F R, Scratch(es), E - Replace 24,00

