


**OPEL Insignia: 1GNI541**

Vinnumber:	<b>WOLGT8ES1E1086899</b>	Versionname:	<b>INSIGNIA BRE ecoFLEX Cosmo 140PK</b>
First Registrationdate:	<b>18/03/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>123809</b>	Power Kw:	<b>103</b>
Bodytype:		Body color:	<b>Silver</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>4231</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

GPS storage		Central consol F
GPS storage	<b>HD</b>	Luggage cover
Windows electric F		Front parking sensors
Windows electric R		Rear parking sensors
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Radio multimedia		
Type of headlighting	<b>Headlighting Xenon</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining leather</b>	
Type of climate control	<b>Autom climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>225/55/17/97 W LightMetal</b>			
Summer tyres:	Fr.L.	<b>Goodyear: 3 mm</b>	Fr.R.	<b>Goodyear: 3 mm</b>
	Re.L.	<b>Bridgestone: 3 mm</b>	Re.R.	<b>Bridgestone: 3 mm</b>

**Assistance equipment**

Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-----------------------	------------	------	------------

Total cost ex VAT	975,59
-------------------	--------

Reflector, Broken, E - Replace	39,60
--------------------------------	-------



Rearlight L, Scratch(es), Acceptable	0,00
--------------------------------------	------

*No pictures to display*

Sill outer R, Bump(s) and scratch(es), LI - Repair and paint (complete)	358,50
---	--------



Tailgate, Scratch(es), Acceptable 0,00

*No pictures to display*

Dashboard, Scratch(es), Acceptable 0,00

*No pictures to display*

Roof pillar R, Scratch(es), Acceptable 0,00

*No pictures to display*

Alloy rim R R, Scratch(es), Acceptable 0,00

*No pictures to display*

Wing R R, Scratch(es), 67 - Polish 55,19



Sill outer L, Bump(s), LI - Repair and paint (complete) 310,50



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Door R R, Scratch(es), Acceptable 0,00

*No pictures to display*