



MERCEDES CLA: 1GQI707

Vinnumber:	WDD1173011N087131	Versionname:	CLA BER 200 CDI 136PK
First Registrationdate:	1/04/2014	Fiscalpower:	
Expertise Mileage:	87224	Power Kw:	100
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2306
Maintenance:	SERV A 290 DGN		
Battery functioning:	Yes		
Number of doors:	4		
Number of seats:	5		
Number head rests:	1		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Sun Roof electric
GPS storage	Central consol F
GPS storage	HD Front parking sensors
Windows electric F	Rear parking sensors
Windows electric R	
Steering wheel multifunctional	
Seats F heated	
Radio multimedia	
Type of headlighting	Headlighting Xenon
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/40/18/92 Y LightMetal			
Summer tyres:	Fr.L.	Bridgestone: 5 mm	Fr.R.	Bridgestone: 5 mm
	Re.L.	Continental: 6 mm	Re.R.	Continental: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	909,20
-------------------	---------------

Alloy rim R L polished, Scratch(es), E - Replace	235,20
--	---------------



Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
---	---------------



Tyre R L, Damaged, E - Replace 132,00



Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim F R polished, Scratch(es), E - Replace 235,20



Alloy rim F L polished, Scratch(es), Acceptable 0,00



Sill outer L, Unclashed, N - Mount/Dismount 0,00

