


MITSUBISHI Outlander: 1GDN031

Vinnumber:	JMBXJGF6WDZ405537	Versionname:	OUTLANDER 2WD Xperience 150PK
First Registrationdate:	8/01/2014	Fiscalpower:	
Expertise Mileage:	62590	Power Kw:	110
Bodytype:	SUV	Body color	Black
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	4203
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Central consol F
GPS storage	SD	Luggage cover
GPS storage		Front parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/55/18/98 H LightMetal			
Summer tyres:	Fr.L.	Toyo: 3 mm	Fr.R.	Toyo: 3 mm
	Re.L.	Toyo: 3 mm	Re.R.	Toyo: 3 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	522,80
-------------------	--------

Alloy rim R L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Alloy rim F L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete)	254,16
---	--------



Door F R, Bump(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Bumper R, Scratch(es), Smart repair	110,00
-------------------------------------	--------



Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Door F L, Bump(s), Acceptable 0,00

No pictures to display

Wing R R, Bump(s), Acceptable 0,00

No pictures to display

Maintenance book, Missing, E - Replace 0,00

No pictures to display

Wing F L, Bump(s), PDR - Knock out without painting 63,00

