



VOLKSWAGEN GOLF VII: 1PBK716

Vinnnumber:	WVWZZAUZGP112258	Versionname:	1.6 TDI 66KW TRENDLINE
First Registrationdate:	30/05/2016	Fiscalpower:	
Expertise Mileage:	40380	Power Kw:	66
Bodytype:		Body color:	Grey
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2407
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F	Luggage cover
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/91 H Steel			
Summer tyres:	Fr.L.	Bridgestone: 6 mm	Fr.R.	Bridgestone: 6 mm
	Re.L.	Bridgestone: 5 mm	Re.R.	Bridgestone: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	458,20
-------------------	--------

Bodywork, Not original part, Remove lettering	0,00
---	------




Ignition key, Missing, E - Replace	150,00
------------------------------------	--------



Door R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Rearview mirror housing L, Scratch(es), Acceptable	0,00
--	------

<i>No pictures to display</i>		
Door R R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Wing R L, Scratch(es), LI - Repair and paint (complete)		308,20
		
Front bumper, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Wing F R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Wheel cover F R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Bumper corner R L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		