



VOLKSWAGEN Golf: 1HDH329

Vinnumber:	WVWZZZAUZEP560842	Versionname:	GOLF VAR Trendline 105PK
First Registrationdate:	24/06/2014	Fiscalpower:	
Expertise Mileage:	70414	Power Kw:	77
Bodytype:		Body color:	Black
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3815
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Sun Roof electric
GPS storage		Panoramic roof
GPS storage	SD	Central consol F
Windows electric F		Luggage cover
Windows electric R		Front parking sensors
Cruise Control		Rear parking sensors
Steering wheel multifunctional		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	
Adaptive cruise control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/91 H LightMetal			
Summer tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Continental: 8,5 mm	Re.R.	Continental: 8,5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	1398,35
-------------------	---------

Door frame R L, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Tailgate, Scratch(es), LI - Repair and paint (complete)	301,68
---	--------



Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete)	115,56
--	--------



Front bumper, Scratch(es), Acceptable 0,00

No pictures to display

Door frame R R, Bump(s), It - Spot repair 115,56



Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Rearlight L, Damaged, E - Replace 114,00



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Wing F L, Scratch(es), Acceptable 0,00

No pictures to display

Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Door F R, Scratch(es), LI - Repair and paint (complete) 318,35



Wing R R, Scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Scratch(es), LI - Repair and paint (complete) 308,20



Mirror side blinker R, Broken, E - Replace 30,00

