


**SKODA SUPERB COMBI: 1KET261**

Vinnumber:	<b>TMBJJ93T7F9053584</b>	Versionname:	<b>1.6 CRTDI 77KW ELEGANCE</b>
First Registrationdate:	<b>16/04/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>163204</b>	Power Kw:	<b>77</b>
Bodytype:		Body color:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2716</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Seats electric R
GPS storage		Seats electric F L
GPS storage	<b>HD</b>	Seats electric F R
Windows electric F		Sun Roof electric
Windows electric R		Panoramic roof
Cruise Control		Central consol F
Steering wheel multifunction		Luggage cover
Seats F heated		Front parking sensors
Radio multimedia		Rear parking sensors
Type of headlighting	<b>Headlighting Xenon</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining leather</b>	
Type of climate control	<b>Autom climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>225/45/17/92 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Uniroyal: 5 mm</b>	Fr.R.	<b>Uniroyal: 5 mm</b>
	Re.L.	<b>Uniroyal: 5 mm</b>	Re.R.	<b>Uniroyal: 5 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------

Total cost ex VAT	353,24
-------------------	--------

Door F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

*No pictures to display*

Reflector, Crack, E - Replace	84,60
-------------------------------	-------



Door R R, Bump(s), Acceptable	0,00
-------------------------------	------

*No pictures to display*

Trunk lid covering R, Scratch(es), Smart repair	110,64
---	--------



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Door R R, Bump(s), PDR - Knock out without painting 63,00



Front bumper, Scratch(es), Acceptable 0,00

No pictures to display