



VOLKSWAGEN Crafter 35 LWB HR: 1GXZ739

| | | | |
|------------------------------------|---------------------------------|--------------|--------------------------------------|
| Vinnnumber: | WV1ZZZ2ZE6030997 | Versionname: | CRAFTER 35 B/F2C LWB HR 136PK |
| First Registrationdate: | 2/06/2014 | Fiscalpower: | |
| Expertise Mileage: | 71178 | Power Kw: | 100 |
| Bodytype: | Transporter | Body color: | Black |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Steel |
| Fueltype: | Diesel | Oil level: | OK |
| Maintenance: | OK | Parking lot: | LCV17 |
| Battery functioning: | Yes | | |
| Number of doors: | 5 | | |
| Number of seats: | 6 | | |
| Number head rests: | 6 | | |
| Rims summer: | Steel | | |
| Category: | Light Commercial Vehicle | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | |
|-------------------------|----------------------------------|
| GPS storage | Central consol F |
| GPS storage | HD |
| Windows electric F | |
| Type of headlighting | Headlighting Halogen |
| Type of GPS | GPS big screen color |
| Type of Lining | Lining artificial leather |
| Type of climate control | Manual climate control |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|------------------------------|-----------------------|-------|-----------------------|
| | 235/65/16/105 R Steel | | | |
| Summer tyres: | Fr.L. | Goodyear: 7 mm | Fr.R. | Goodyear: 7 mm |
| | Re.L. | Goodyear: 7 mm | Re.R. | Goodyear: 7 mm |

Assistance equipment

| | | | |
|-------------|------------|------|------------|
| Spare wheel | Yes | Jack | Yes |
|-------------|------------|------|------------|

| | |
|--------------------------|----------------|
| Total cost ex VAT | 1350,26 |
|--------------------------|----------------|

| | |
|--|---------------|
| Trunk door R R, Bump(s) and scratch(es), LI - Repair and paint (complete) | 346,00 |
|--|---------------|



| | |
|--|---------------|
| Sill outer R, Bump(s) and scratch(es), LI - Repair and paint (complete) | 328,88 |
|--|---------------|



Bumper R, Bump(s) and scratch(es), E - Replace 329,40



Bodywork, Not original part, Acceptable 0,00

No pictures to display

Interior, Not original part, Acceptable 0,00



Trunk door R L, Bump(s) and scratch(es), LI - Repair and paint (complete) 346,00

