



## VOLKSWAGEN GOLF VII: 1PBK848

Vinnnumber:	<b>WVWZZZAUZGP113545</b>	Versionname:	<b>1.6 TDI 66KW TRENDLINE</b>
First Registrationdate:	<b>30/05/2016</b>	Fiscalpower:	
Expertise Mileage:	<b>54217</b>	Power Kw:	<b>66</b>
Bodytype:		Body color:	<b>Grey</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3707</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

## Options

Windows electric F	Luggage cover
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting:	<b>Headlighting Halogen</b>
Type of Lining:	<b>Lining fabrics</b>
Type of climate control:	<b>Manual climate control</b>

## Limited Technical Inspection

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

## Degree of wear

	<b>195/65/15/91 H Steel</b>			
Summer tyres:	Fr.L.	<b>Bridgestone: 2 mm</b>	Fr.R.	<b>Bridgestone: 2 mm</b>
	Re.L.	<b>Bridgestone: 7 mm</b>	Re.R.	<b>Bridgestone: 7 mm</b>

## Assistance equipment

Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-----------------------	------------	------	------------

Total cost ex VAT	<b>857,15</b>
-------------------	---------------

Wheel cover R R, Scratch(es), Acceptable	<b>0,00</b>
--	-------------

*No pictures to display*

Tyre F L, Damaged, E - Replace	<b>132,00</b>
--------------------------------	---------------



Bumper R, Scratch(es), Acceptable	<b>0,00</b>
-----------------------------------	-------------

*No pictures to display*

Door F R, Scratch(es), LI - Repair and paint (complete)	<b>318,35</b>
---	---------------



Tyre F R, Damaged, E - Replace

132,00



Wheel cover F R, Scratch(es), Acceptable

0,00

No pictures to display

Wing R R, Bump(s), PDR - Knock out without painting

63,00



Front bumper, Scratch(es), LI - Repair and paint (complete)

211,80



Bodywork, Not original part, Remove lettering

0,00



Door R L, Scratch(es), Acceptable

0,00

No pictures to display