



VOLKSWAGEN Passat: 1HAB016

Vinnnumber:	WVWZZZ3CZEE164612	Versionname:	PASSAT VAR Comfortline
First Registrationdate:	2/06/2014	Fiscalpower:	136PK
Expertise Mileage:	133592	Power Kw:	100
Bodytype:	Break	Body color:	Dark Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4413
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Sun Roof electric
Windows electric F	Central consol F
Windows electric R	Luggage cover
Cruise Control	Front parking sensors
Steering wheel multifunctional	Rear parking sensors
Seats F heated	
Radio multimedia	
Type of headlighting:	Headlighting Xenon
Type of GPS:	GPS big screen color
Type of Lining:	Lining leather
Type of climate control:	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

215/55/16/97 W LightMetal				
Summer tyres:	Fr.L.	Bridgestone: 3 mm	Fr.R.	Bridgestone: 3 mm
	Re.L.	Bridgestone: 4 mm	Re.R.	Bridgestone: 4 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	612,52
-------------------	---------------

Door R L, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
---	---------------



Door R R, Scratch(es), Acceptable	0,00
-----------------------------------	-------------


No pictures to display

Wing R L, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Bonnet, Chemical pollution, LI - Repair and paint (complete)	290,08
--	---------------

Scratch(es), chemical pollution, E - Repair and paint (complete) 0,00



Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Bump(s), Acceptable 0,00

No pictures to display

Rear window, Scratch(es), E - Replace 0,00



Door panel F L, Damaged, Smart repair 110,64

