



|                              |                          |              |                                 |
|------------------------------|--------------------------|--------------|---------------------------------|
| <b>TOYOTA Verso: 1EWQ939</b> |                          |              |                                 |
| Vinnnumber:                  | <b>NMTDD26R50R081449</b> | Versionname: | <b>VERSO Skyview 5pl. 126PK</b> |
| First Registrationdate:      | <b>9/04/2013</b>         | Fiscalpower: |                                 |
| Expertise Mileage:           | <b>105315</b>            | Power Kw:    | <b>91</b>                       |
| Bodytype:                    |                          | Body color:  | <b>Grey</b>                     |
| Gearbox:                     | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>                  |
| Transmission:                | <b>Front</b>             | Rims summer: | <b>Aluminium</b>                |
| Fueltype:                    | <b>Diesel</b>            | Oil level:   | <b>OK</b>                       |
| Maintenance:                 | <b>OK</b>                | Parking lot: | <b>2414</b>                     |
| Battery functioning:         | <b>Yes</b>               |              |                                 |
| Number of doors:             | <b>5</b>                 |              |                                 |
| Number of seats:             | <b>5</b>                 |              |                                 |
| Number head rests:           | <b>5</b>                 |              |                                 |
| Rims summer:                 | <b>Aluminium</b>         |              |                                 |
| Category:                    | <b>Passenger Car</b>     |              |                                 |
| Oil level:                   | <b>OK</b>                |              |                                 |

|                                |                             |                      |  |
|--------------------------------|-----------------------------|----------------------|--|
| <b>Options</b>                 |                             |                      |  |
| Radio CD                       |                             | Panoramic roof       |  |
| GPS storage                    |                             | Central consol F     |  |
| GPS storage                    | <b>HD</b>                   | Luggage cover        |  |
| Windows electric F             |                             | Rear parking sensors |  |
| Windows electric R             |                             |                      |  |
| Cruise Control                 |                             |                      |  |
| Steering wheel multifunctional |                             |                      |  |
| Radio multimedia               |                             |                      |  |
| Type of headlighting           | <b>Headlighting Halogen</b> |                      |  |
| Type of GPS                    | <b>GPS big screen color</b> |                      |  |
| Type of Lining                 | <b>Lining fabrics</b>       |                      |  |

|                                     |           |                     |            |
|-------------------------------------|-----------|---------------------|------------|
| <b>Limited Technical Inspection</b> |           |                     |            |
| Airco functioning                   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile                  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position                       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime                 | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass                        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake                           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                                     |           | Lighting            | <b>OK</b>  |
|                                     |           | Wiperblades         | <b>OK</b>  |

|                       |                                  |                       |       |                       |
|-----------------------|----------------------------------|-----------------------|-------|-----------------------|
| <b>Degree of wear</b> |                                  |                       |       |                       |
|                       | <b>205/60/16/92 H LightMetal</b> |                       |       |                       |
| Summer tyres:         | Fr.L.                            | <b>Michelin: 5 mm</b> | Fr.R. | <b>Michelin: 5 mm</b> |
|                       | Re.L.                            | <b>Michelin: 5 mm</b> | Re.R. | <b>Michelin: 5 mm</b> |

|   |            |            |               |
|---|------------|------------|---------------|
| <b>Assistance equipment</b>                                       |            |            |               |
| Repair kit  | <b>Yes</b> | Compressor | <b>Yes</b>    |
| <b>Total cost ex VAT</b>  |            |            | <b>423,60</b> |
| <b>Front bumper, Bad repair, LI - Repair and paint (complete)</b> |            |            | <b>211,80</b> |



|  |  |  |               |
|--|--|--|---------------|
| <b>Bumper R, Scratch(es), LI - Repair and paint (complete)</b> |  |  | <b>211,80</b> |
|--|--|--|---------------|



Wing F R, Scratch(es), Acceptable 0,00



Alloy rim R L, Scratch(es), Acceptable 0,00



Bonnet, Bad repair, Acceptable 0,00



Wing R L, Scratch(es), Acceptable 0,00

