



VOLVO V60: 1GSX009

Vinnnumber:	YV1FW8481E1208664	Versionname:	V60 BRE D2 Kinetic 115PK
First Registrationdate:	18/04/2014	Fiscalpower:	
Expertise Mileage:	163140	Power Kw:	84
Bodytype:	Break	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2119
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
GPS storage		Luggage cover
GPS storage	HD	Rear parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/92 H LightMetal			
Summer tyres:	Fr.L.	Bridgestone: 2 mm	Fr.R.	Bridgestone: 2 mm
	Re.L.	Michelin: 2 mm	Re.R.	Michelin: 2 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	2296,08
Sill trim R, Missing, E - Replace	422,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00
--	--------------



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Door F L, Bump(s) and scratch(es), LI - Repair and paint (complete) 318,35



Wheel arch cover R R, Broken, E - Replace 95,00



Front bumper, Scratch(es), It - Spot repair 115,56



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Door R R, Scratch(es), LI - Repair and paint (complete) 318,35



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Wing R R, Bump(s), Acceptable 0,00

No pictures to display

Wing F L, Bump(s) and scratch(es), Le - Replace and paint 530,02



Door F R, Bump(s), Acceptable 0,00

No pictures to display