



## VOLKSWAGEN Passat: 1HHZ105

Vinnnumber:	<b>WVWZZZ3CZDP051408</b>	Versionname:	<b>PASSAT BER Trendline BM</b>
First Registrationdate:	<b>22/05/2013</b>	Fiscalpower:	<b>105PK</b>
Expertise Mileage:	<b>105237</b>	Power Kw:	<b>77</b>
Bodytype:	<b>Berline</b>	Body color:	<b>Blue</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2108</b>
Number of doors:	<b>4</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

## Options

Radio CD		Central consol F
GPS storage	<b>HD</b>	Front parking sensors
GPS storage		Rear parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Radio multimedia		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining fabrics</b>	
Type of climate control	<b>Autom climate control</b>	

## Limited Technical Inspection

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

## Degree of wear

	<b>205/55/16/91 H LightMetal</b>			
Summer tyres:	Fr.L.	<b>Bridgestone: 3 mm</b>	Fr.R.	<b>Bridgestone: 3 mm</b>
	Re.L.	<b>Bridgestone: 4 mm</b>	Re.R.	<b>Bridgestone: 4 mm</b>

## Assistance equipment

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------

Total cost ex VAT	438,60
-------------------	--------

Windscreen, Repaired, Acceptable	0,00
----------------------------------	------

No pictures to display



Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Door F R, Repaired, Acceptable	0,00
--------------------------------	------

No pictures to display

Alloy rim F R, Scratch(es), Acceptable	0,00
--	------

<i>No pictures to display</i>		
Front bumper, Scratch(es), LI - Repair and paint (complete)		211,80
		
Alloy rim F L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Tailgate, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Bonnet, Bump(s), Acceptable		0,00
<i>No pictures to display</i>		
Trunk lid covering R, Missing, E - Replace		15,00
		
Wing F L, Bump(s), Acceptable		0,00
<i>No pictures to display</i>		
Rearview mirror housing L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		