



AUDI A1: 1FEK056

Vinnumber:	WAUZZZ8X1EB000441	Versionname:	A1 SB Attraction 105PK
First Registrationdate:	6/06/2013	Fiscalpower:	
Expertise Mileage:	91610	Power Kw:	77
Bodytype:		Body color:	Black
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance	OK	Parking lot:	3809
Maintenance	1100		
Maintenance	243 DAGEN		
Battery functioning	Yes		
Number of doors	5		
Number of seats	4		
Number head rests	4		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options

Radio CD	Luggage cover
Windows electric F	Rear parking sensors
Windows electric R	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/15/88 V LightMetal			
Summer tyres:	Fr.L.	Dunlop: 6 mm	Fr.R.	Dunlop: 6 mm
	Re.L.	Dunlop: 5 mm	Re.R.	Dunlop: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	623,00
-------------------	---------------

Seat cover R, Stain, Cleaning	25,00
-------------------------------	--------------




Sill trim R L, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display	
Maintenance, Maintenance, Acceptable	0,00



Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete) 217,44



Bonnet, Stone chip(s), Acceptable 0,00

No pictures to display

Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Wing F L, Scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Bump(s) and scratch(es), Acceptable 0,00

No pictures to display

Windscreen, Stone chip(s), Acceptable 0,00

No pictures to display

Door frame R R, Scratch(es), Acceptable 0,00

No pictures to display

Glove compartment lid, Scratch(es), E - Replace 240,00



Seat cover F R, Stain, Cleaning 25,00



Wing R R, Scratch(es), Acceptable 0,00

No pictures to display

Trunk lid covering R, Scratch(es), Acceptable 0,00

No pictures to display

Rearview mirror housing R, Scratch(es), Acceptable 0,00

No pictures to display

Wing F R, Bump(s) and scratch(es), Acceptable 0,00

No pictures to display

Door panel F R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F R, Scratch(es), Acceptable 0,00

No pictures to display


Door R L, Bump(s) and scratch(es), Acceptable 0,00

No pictures to display

Door R R, Bump(s) and scratch(es), Acceptable 0,00

No pictures to display

Outer door handle F R, Scratch(es), Acceptable 0,00

Outer door handle R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Front bumper, Scratch(es), It - Spot repair	115,56
	
Rear bulkhead lining, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Sill trim R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	