



BMW 6 GRAN COUPE: GA4472

Vinnnumber:	WBA6A81090D369188	Versionname:	3.0 640D XDRIVE 4WD GRAN COUPE AUTO
First Registrationdate:	7/01/2015	Fiscalpower:	
Expertise Mileage:	37065	Power Kw:	230
Bodytype:	Berline	Body color:	Dark Brown
Gearbox:	Automatic	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1110
Number of doors:	4		
Number of seats:	5		
Number head rests:	4		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Seats electric F L
Windows electric F	Seats electric F R
Windows electric R	Central consol F
Cruise Control	Front parking sensors
Steering wheel multifunction	Rear parking sensors
Seats F heated	
Type of headlighting:	Headlighting Xenon
Type of GPS:	GPS big screen color
Type of Lining:	Lining leather
Type of climate control:	Autom climate control
Head-up Display	
Sport seats	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

245/40/19/94 Y LightMetal				
Summer tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Runflat	Yes
---------	------------

Total cost ex VAT	634,16
--------------------------	---------------

Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
---	--------------



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
---	--------------



Front bumper, Scratch(es), LI - Repair and paint (complete)

254,16



Wing R L, Scratch(es), Acceptable

0,00

No pictures to display

Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Wing R R, Scratch(es), Acceptable

0,00

No pictures to display