



**BMW 5: 1GNP817**

Vinnumber:	<b>WBA5J11090D335982</b>	Versionname:	<b>5 TOURING 518d 136PK</b>
First Registrationdate:	<b>19/03/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>183739</b>	Power Kw:	<b>100</b>
Bodytype:	<b>Break</b>	Body color	<b>.</b>
Gearbox:	<b>MAN 6 VIT</b>	Body color	<b>Blue</b>
Transmission:	<b>Back</b>	Paint type	<b>Metalic</b>
Fueltype:	<b>Diesel</b>	Rims summer	<b>Aluminium</b>
Battery functioning	<b>Yes</b>	Oil level	<b>OK</b>
Number of doors	<b>5</b>	Parking lot	<b>.4116</b>
Number of seats	<b>5</b>		
Number head rests	<b>5</b>		
Rims summer	<b>Aluminium</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		
Registration Certificate Car (BE)	<b>Yes</b>		

**Options**

Radio CD		Seats electric F L	
GPS storage		Seats electric F R	
GPS storage	<b>HD</b>	Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional			
Type of headlighting	<b>Headlighting Xenon</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining leather</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>225/55/17/97 H LightMetal</b>				
Winter tyres:	Fr.L.	<b>Bridgestone: 7 mm</b>	Fr.R.	<b>Bridgestone: 7 mm</b>
	Re.L.	<b>Continental: 5 mm</b>	Re.R.	<b>Continental: 5 mm</b>

**Assistance equipment**





















Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

Total cost ex VAT	<b>718,88</b>
-------------------	---------------

Door F L, Bump(s), Acceptable	<b>0,00</b>
-------------------------------	-------------



Front bumper, Bump(s) and scratch(es), LI - Repair and paint (complete)	<b>254,16</b>
---	---------------

			Wing F L, Scratch(es), Acceptable	0,00
			Alloy rim F L, Scratch(es), Acceptable	0,00
			Bonnet, Stone chip(s), Acceptable	0,00
			Windscreen, Stone chip(s), Windscreen repair	0,00
			Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete)	254,16
			Alloy rim R L, Scratch(es), Acceptable	0,00
			Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
			Spoiler R, Scratch(es), It - Spot repair	115,56
			Wing R R, Bump(s), Acceptable	0,00

