



AUDI Q5: 1HGV123

Vinnnumber:	WAUZZZ8R1FA007916	Versionname:	Q5 136PK
First Registrationdate:	17/07/2014	Fiscalpower:	
Expertise Mileage:	150915	Power Kw:	100
Bodytype:	SUV	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3323
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
GPS storage	HD	Luggage cover
GPS storage		Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection













Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	235/65/17/108 V LightMetal			
Summer tyres:	Fr.L.	Dunlop: 2 mm	Fr.R.	Dunlop: 2 mm
	Re.L.	Dunlop: 2 mm	Re.R.	Dunlop: 2 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			780,12
Ignition key, Missing, E - Replace			150,00
<i>No pictures to display</i>			
Wing R R, Bump(s), Acceptable			0,00
<i>No pictures to display</i>			
Maintenance book, Missing, E - Replace			0,00
<i>No pictures to display</i>			
Rear spoiler, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Door R R, Bump(s), Acceptable			0,00
<i>No pictures to display</i>			
Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete)			369,84

			Bumper grille, Broken, E - Replace	34,08
			Bumper R, Scratch(es), Smart repair	110,64
			Bumper F R, Scratch(es), It - Spot repair	115,56
			Windscreen, Repaired, Acceptable	0,00
			Door F R, Bump(s), Acceptable	0,00
<i>No pictures to display</i>				
Bumper R, Scratch(es), Acceptable				0,00
<i>No pictures to display</i>				