



CITROEN Berlingo: 1HBR032

Vinnnumber:	VF77D9HF0EJ656452	Versionname:	BERLINGO B/F Kort Fresh 90PK
First Registrationdate:	12/06/2014	Fiscalpower:	
Expertise Mileage:	130706	Power Kw:	66
Bodytype:	Transporter	Body color:	White
Gearbox:	MAN 5 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2522
Maintenance:	IN 7900 KM		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	
Windows electric F	
Type of headlighting	Headlighting Halogen
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/70/15/102 R Steel			
Winter tyres:	Fr.L.	Pirelli: 7 mm	Fr.R.	Pirelli: 7 mm
	Re.L.	Pirelli: 9,9 mm	Re.R.	Pirelli: 9,9 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	1430,86
-------------------	----------------

Ignition key, Missing, E - Replace	150,00
------------------------------------	---------------



Wheel cover R L, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Wheel cover F R, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Roof, Bump(s), PDR - Knock out without painting	82,80
---	--------------



Wheel cover F L, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 382,76



Wing R L, Scratch(es), LI - Repair and paint (complete) 231,15



Gear shift lever cover, Missing, E - Replace 9,00



Bumper R, Bump(s), Acceptable 0,00

No pictures to display

Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 375,15



Rearview mirror housing R, Scratch(es), Acceptable 0,00

No pictures to display

Trunk door R L, Scratch(es), Acceptable 0,00

No pictures to display

Front bumper, Scratch(es), Acceptable 0,00

No pictures to display

Interior, Stain, Cleaning 25,00





Trunk door R R, Accident, LI - Repair and paint (partial) 175,00

