



AUDI A5: RM9781			
Vinnumber:	WAUZZZ8T5EA047443	Versionname:	A5 SB DPF Multitr.204PK Aut.
First Registrationdate:	24/02/2014	Fiscalpower:	
Expertise Mileage:	109437	Power Kw:	150
Bodytype:		Body color	Black
Gearbox:	Automatic	Paint type	Metalic
Transmission:		Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	2712
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options	
Radio CD	Central consol F
Windows electric F	Rear parking sensors
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Seats F heated	
Radio multimedia	
Type of headlighting	Headlighting Xenon
Type of GPS	GPS big screen color
Type of Lining	Lining leather and alcantara
Type of climate control	Autom climate control
Sport seats	

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK


Degree of wear				
Winter tyres:	245/40/18/97 V LightMetal			
	Fr.L.	Continental: 3 mm	Fr.R.	Continental: 3 mm
	Re.L.	Continental: 6 mm	Re.R.	Continental: 6 mm

Assistance equipment	
Jack	Yes
Total cost ex VAT	2101,55
Wing F L, Scratch(es), Acceptable	0,00

<i>No pictures to display</i>	
Wing R L, Bump(s), PDR - Knock out without painting	63,00



Roof, Chemical polution, LI - Repair and paint (complete)	577,80
---	---------------



Wing R R, Scratch(es), Acceptable 0,00

No pictures to display


Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Windscreen, Damaged, E - Replace 560,64




Tailgate, Chemical pollution, LI - Repair and paint (complete) 362,02



Bonnet, Chemical pollution, LI - Repair and paint (complete) 348,09



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Door R L, Scratch(es), Acceptable 0,00

No pictures to display