


DACIA Lodgy: 1FBO110

Vinnnumber:	UU1JSDBC648919944	Versionname:	LODGY Laur?ate 7pl.
First Registrationdate:	16/05/2013	Fiscalpower:	107PK
Expertise Mileage:	155646	Power Kw:	79
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2723
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		

Options

GPS storage	HD	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	Tow bar fixed
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

185/65/15/88 T Steel				
Summer tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	1845,02
-------------------	---------

Wheel cover R R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete)	169,44
---	--------



Door F L, Scratch(es), LI - Repair and paint (complete)	254,68
---	--------



Door frame F L, Bump(s) and scratch(es), It - Spot repair 115,56



Bonnet, Bump(s) and scratch(es), LI - Repair and paint (complete) 232,06



Door R L, Scratch(es), LI - Repair and paint (complete) 254,68



Wheel cover F R, Damaged, E - Replace 24,00



Wheel cover F L, Scratch(es), Acceptable 0,00

No pictures to display

Door frame R R, Bump(s) and scratch(es), It - Spot repair 115,56



Tailgate, Scratch(es), LI - Repair and paint (complete) 241,34



Wing F L, Scratch(es), LI - Repair and paint (complete) 176,14



Reflector, Damaged, E - Replace 15,00



Wing R L, Scratch(es), LI - Repair and paint (complete)	246,56
---	--------



Front bumper, Scratch(es), Acceptable	0,00
---------------------------------------	------

No pictures to display

Wing F R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Ignition key, Not functioning (well), Repair/replace (lump sum)	0,00
---	------



Wing R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display