


**BMW 3: 1HAZ395**

Vinnumber:	<b>WBA3K91070F935102</b>	Versionname:	<b>3 TOURING 316d 116PK</b>
First Registrationdate:	<b>6/06/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>140619</b>	Power Kw:	<b>85</b>
Bodytype:	<b>Break</b>	Body color:	<b>Red</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Opaque</b>
Transmission:	<b>Back</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>2113</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F
GPS storage	<b>HD</b>	Luggage cover
GPS storage		Rear parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Radio multimedia		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining leather</b>	
Type of climate control	<b>Autom climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>225/50/17/94 W LightMetal</b>			
Summer tyres:	Fr.L.	<b>Bridgestone: 6 mm</b>	Fr.R.	<b>Bridgestone: 6 mm</b>
	Re.L.	<b>Bridgestone: 4 mm</b>	Re.R.	<b>Bridgestone: 8 mm</b>

**Assistance equipment**

	Runflat	<b>Yes</b>
Total cost ex VAT		<b>413,50</b>
Front bumper, Scratch(es), Acceptable		<b>0,00</b>
<i>No pictures to display</i>		
Seat cover F L, Damaged, Acceptable		<b>0,00</b>
<i>No pictures to display</i>		
Rocker panel inner R R, Damaged, Acceptable		<b>0,00</b>
<i>No pictures to display</i>		
Door F L, Scratch(es), Acceptable		<b>0,00</b>
<i>No pictures to display</i>		
Roof, Bump(s) and scratch(es), Acceptable		<b>0,00</b>
<i>No pictures to display</i>		
Sill outer R, Scratch(es), LI - Repair and paint (complete)		<b>310,50</b>



Bonnet, Stone chip(s), Acceptable	0,00
<i>No pictures to display</i>	
Wing R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing R R, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00



Alloy rim R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Rear wiper arm, Incomplete, E - Replace	8,00

