


BMW 5: 1GWN846

Vinnumber:	WBA5C31050D048578	Versionname:	5 BER 520dA 163PK Aut.
First Registrationdate:	20/05/2014	Fiscalpower:	
Expertise Mileage:	124043	Power Kw:	120
Bodytype:		Body color	Dark Grey
Gearbox:	Automatic	Paint type	Metalic
Transmission:		Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	2128
Number of doors	4		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Sun Roof electric
Windows electric F	Central consol F
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Seats F heated	
Radio multimedia	
Type of headlighting	Headlighting LED
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control
Sport seats	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/55/17/97 Y LightMetal			
Summer tyres:	Fr.L.	Pirelli: 4 mm	Fr.R.	Pirelli: 4 mm
	Re.L.	Pirelli: 4 mm	Re.R.	Pirelli: 4 mm

Assistance equipment

 Runflat **Yes**

 Total cost ex VAT **1267,98**

 Wing R L, Chemical polution, Acceptable **0,00**
No pictures to display

 Protection plate M, Tear, E - Replace **74,00**

 Door R R, Chemical polution, Acceptable **0,00**
No pictures to display

 Bumper F R, Scratch(es), Acceptable **0,00**
No pictures to display

Wing R R, Chemical polution, Acceptable 0,00

No pictures to display


Bonnet, Stone chip(s), Acceptable 0,00

No pictures to display

Roof, Chemical polution, LI - Repair and paint (complete) 577,80



Tailgate, Chemical polution, LI - Repair and paint (complete) 362,02



Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete) 254,16

