



**BMW 3: 1GSY173**

Vinnumber:	<b>WBA3K11010F831917</b>	Versionname:	<b>3 TOURING 318d 136PK</b>
First Registrationdate:	<b>22/04/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>120389</b>	Power Kw:	<b>100</b>
Bodytype:		Body color:	<b>Dark Blue</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Back</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>1710</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F
GPS storage	<b>HD</b>	Luggage cover
GPS storage		Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining leather</b>	
Type of climate control	<b>Autom climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**



	<b>205/60/16/92 W LightMetal</b>			
Summer tyres:	Fr.L.	<b>Goodyear: 3 mm</b>	Fr.R.	<b>Goodyear: 3 mm</b>
	Re.L.	<b>Goodyear: 3 mm</b>	Re.R.	<b>Goodyear: 3 mm</b>

**Assistance equipment**

Compressor	<b>Yes</b>
------------	------------

Total cost ex VAT	<b>240,80</b>
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	<b>95,00</b>



Wing R L, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	
Wing R R, Bump(s) and scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door F L, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	
Door F R, Bump(s), PDR - Knock out without painting	82,80
	
Door R R, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	
Bumper R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door R L, Bump(s), PDR - Knock out without painting	63,00
	
Alloy rim R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	