



LEXUS CT 200 H: 1NUN676

Vinnnumber:	JTHKD5BHX02272393	Versionname:	1.8 F-SPORT LINE AUTO
First Registrationdate:	29/04/2016	Fiscalpower:	
Expertise Mileage:	37101	Power Kw:	73
Bodytype:		Body color:	White
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Hybrid Petrol	Oil level:	OK
Maintenance:	33051	Parking lot:	2731
Maintenance:	15/05/2018		
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L	
GPS storage	HD	Seats electric F R	
GPS storage		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		
Sport seats			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/45/17/87 W LightMetal			
Summer tyres:	Fr.L.	Yokohama: 6 mm	Fr.R.	Yokohama: 6 mm
	Re.L.	Yokohama: 6 mm	Re.R.	Yokohama: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT

	1011,35
Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete)	95,00





Front bumper, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim R R polished, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete) 95,00



Backrest cover F R, Damaged, E - Replace 360,00



Door F L, Bump(s), LI - Repair and paint (complete) 366,35

