



BMW 5: 1HUH759

Vinnumber:	WBA5E51030D675026	Versionname:	5 BER 520d 163PK
First Registrationdate:	6/10/2014	Fiscalpower:	
Expertise Mileage:	83685	Power Kw:	120
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	1109
Battery functioning:	Yes		
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
GPS storage		Front parking sensors
GPS storage	HD	Rear parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Type of headlighting	Headlighting Xenon	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear


	225/55/17/97 Y LightMetal			
Summer tyres:	Fr.L.	Michelin: 7 mm	Fr.R.	Michelin: 7 mm
	Re.L.	Bridgestone: 5 mm	Re.R.	Bridgestone: 5 mm

Assistance equipment

Runflat	Yes
---------	------------

Total cost ex VAT	627,32
-------------------	---------------

Front bumper, Scratch(es), LI - Repair and paint (complete)	254,16
---	---------------





Door R R, Bump(s), PDR - Knock out without painting 111,00



Alloy rim F R, Scratch(es), Acceptable 0,00

No pictures to display

Wheel hub cap R R, Missing, E - Replace 8,00



Alloy rim F L, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete) 254,16



Wing R L, Scratch(es), Acceptable 0,00

No pictures to display