


BMW 520 D: 1FHO807

Vinnnumber:	WBAFW11010D270521	Versionname:	5 BER 520dA Start/Stop
First Registrationdate:	1/07/2013	Fiscalpower:	163PK aut
Expertise Mileage:	151227	Power Kw:	120
Bodytype:		Body color:	Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	4703
Battery functioning:	Yes		
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Seats electric F L
GPS storage	HD	Seats electric F R
GPS storage		Central consol F
Windows electric F		Front parking sensors
Windows electric R		Rear parking sensors
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Type of headlighting	Headlighting Xenon	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/55/17/97 W LightMetal			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 3 mm	Re.R.	Michelin: 3 mm

Assistance equipment

	Runflat	No
Total cost ex VAT		278,16
Door R R, Repaired, Acceptable		0,00
<i>No pictures to display</i>		
Wing R L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Alloy rim F L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Windscreen, Stone chip(s), Windscreen repair		0,00
<i>No pictures to display</i>		
Alloy rim R R, Scratch(es), Acceptable		0,00



No pictures to display

Door F R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Alloy rim F R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Alloy rim R L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Tires, Not original part, P - Check	0,00
-------------------------------------	------



Wing R R, Repaired, Acceptable	0,00
--------------------------------	------

No pictures to display

Front bumper, Bump(s) and scratch(es), LI - Repair and paint (complete)	278,16
---	--------

