



BMW 3: 1HAG014			
Vinnumber:	WBA3K71050F272519	Versionname:	3 TOURING 325d 211PK
First Registrationdate:	3/06/2014	Fiscalpower:	
Expertise Mileage:	177832	Power Kw:	155
Bodytype:	Break	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2330
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Xenon
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	225/50/17/94 W LightMetal			
Summer tyres:	Fr.L.	Bridgestone: 7 mm	Fr.R.	Bridgestone: 7 mm
	Re.L.	Michelin: 3 mm	Re.R.	Michelin: 3 mm

Assistance equipment	
Total cost ex VAT	2011,93
Bonnet, Chemical polution, LI - Repair and paint (complete)	290,08



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Door F L, Bump(s) and scratch(es), LI - Repair and paint (complete)	318,35
---	--------

			Front bumper, Bump(s) and scratch(es), LI - Repair and paint (complete)	211,80
			Roof, Chemical pollution, LI - Repair and paint (complete)	481,50
			Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete)	308,20
			Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
			Foglight R, Damaged, E - Replace	138,00
			Door R R, Scratch(es), Acceptable	0,00
No pictures to display				
			Sill outer R, Strained , I - Repair	74,00