


**BMW 3: 1HCR769**

|                                    |                          |              |                             |
|------------------------------------|--------------------------|--------------|-----------------------------|
| Vinnumber:                         | <b>WBA3K11050F833296</b> | Versionname: | <b>3 TOURING 318d 136PK</b> |
| First Registrationdate:            | <b>19/06/2014</b>        | Fiscalpower: |                             |
| Expertise Mileage:                 | <b>110194</b>            | Power Kw:    | <b>100</b>                  |
| Bodytype:                          |                          | Body color:  | <b>Brown</b>                |
| Gearbox:                           | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>              |
| Transmission:                      |                          | Rims summer: | <b>Aluminium</b>            |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                   |
| Maintenance:                       | <b>OK</b>                | Parking lot: | <b>3212</b>                 |
| Battery functioning:               | <b>Yes</b>               |              |                             |
| Number of doors:                   | <b>5</b>                 |              |                             |
| Number of seats:                   | <b>5</b>                 |              |                             |
| Number head rests:                 | <b>5</b>                 |              |                             |
| Rims summer:                       | <b>Aluminium</b>         |              |                             |
| Category:                          | <b>Passenger Car</b>     |              |                             |
| Oil level:                         | <b>OK</b>                |              |                             |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                             |

**Options**

|                                |                              |                       |
|--------------------------------|------------------------------|-----------------------|
| Radio CD                       |                              | Central consol F      |
| GPS storage                    |                              | Luggage cover         |
| GPS storage                    | <b>HD</b>                    | Front parking sensors |
| Windows electric F             |                              | Rear parking sensors  |
| Cruise Control                 |                              |                       |
| Steering wheel multifunctional |                              |                       |
| Type of headlighting           | <b>Headlighting Halogen</b>  |                       |
| Type of GPS                    | <b>GPS big screen color</b>  |                       |
| Type of Lining                 | <b>Lining fabrics</b>        |                       |
| Type of climate control        | <b>Autom climate control</b> |                       |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

| 205/60/16/98 W LightMetal |       |                          |       |                          |
|---------------------------|-------|--------------------------|-------|--------------------------|
| Summer tyres:             | Fr.L. | <b>Bridgestone: 3 mm</b> | Fr.R. | <b>Bridgestone: 3 mm</b> |
|                           | Re.L. | <b>Bridgestone: 3 mm</b> | Re.R. | <b>Bridgestone: 3 mm</b> |

**Assistance equipment**

|            |            |            |            |
|------------|------------|------------|------------|
| Repair kit | <b>Yes</b> | Compressor | <b>Yes</b> |
|------------|------------|------------|------------|

|                   |        |
|-------------------|--------|
| Total cost ex VAT | 865,56 |
|-------------------|--------|

|   |        |
|---|--------|
| Bumper F L, Scratch(es), It - Spot repair | 115,56 |
|---|--------|



|  |      |
|--|------|
| Alloy rim F R, Scratch(es), Acceptable | 0,00 |
|--|------|

*No pictures to display*

|                                   |      |
|-----------------------------------|------|
| Bumper R, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

*No pictures to display*

|                                |        |
|--------------------------------|--------|
| Foglight R, Crack, E - Replace | 138,00 |
|--------------------------------|--------|



Door F L, Bump(s), PDR - Knock out without painting 63,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Tailgate, Scratch(es), LI - Repair and paint (complete) 301,68



Roof, Bump(s), PDR - Knock out without painting 63,00



Seat cover R L, Stain, Cleaning 25,00



Floor covering F L, Damaged, Smart repair 64,32

