


BMW 3: 1FDE056

Vinnumber:	WBA3K11080F824379	Versionname:	3 TOURING 318d 136PK
First Registrationdate:	29/05/2013	Fiscalpower:	
Expertise Mileage:	156733	Power Kw:	100
Bodytype:	Break	Body color:	Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	1214
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	No		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	HD	Rear parking sensors	
Windows electric F		Type of Tow bar	Tow bar removable
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/55/16/95 W LightMetal			
Summer tyres:	Fr.L.	Dunlop: 3 mm	Fr.R.	Dunlop: 3 mm
	Re.L.	Dunlop: 3 mm	Re.R.	Dunlop: 3 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	2667,71
Backrest cover R L, Scratch(es), Smart repair	64,32



Door F R, Bump(s), Acceptable	0,00
-------------------------------	-------------

No pictures to display

Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
---	---------------



Door F L, Bad repair, Paint 0,00



Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete) 211,80



Roof, Bump(s), PDR - Knock out without painting 63,00



Sill outer L, Scratch(es), LI - Repair and paint (complete) 310,50



Door panel R R, Scratch(es), Smart repair 110,64



Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete) 308,20



Bonnet, Bump(s) and scratch(es), LI - Repair and paint (complete) 290,08



Sill outer R, Scratch(es), LI - Repair and paint (complete) 310,50



Seat cover R R, Damaged, Acceptable 0,00



Seat cover R L, Damaged, Acceptable 0,00



Trunk lid covering R, Scratch(es), Acceptable 0,00

No pictures to display

Backrest cover R R, Scratch(es), Smart repair 64,32



Wing F R, Bad repair, Paint 0,00



Door R L, Bad repair, Paint 0,00





Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 308,20



Backrest cover F L, Damaged, Acceptable 0,00



Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 414,35

