



**KIA Sportage: 1GCX743**

Vinnnumber:	<b>U5YPC815ADL413943</b>	Versionname:	<b>SPORTAGE 2WD iTouch</b>
First Registrationdate:	<b>3/01/2014</b>	Fiscalpower:	<b>115PK</b>
Expertise Mileage:	<b>131891</b>	Power Kw:	<b>85</b>
Bodytype:	<b>SUV</b>	Body color:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2411</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	Sun Roof electric	
Windows electric F	Panoramic roof	
Windows electric R	Central consol F	
Cruise Control	Luggage cover	
Steering wheel multifunctional	Front parking sensors	
Radio multimedia	Rear parking sensors	
Type of headlighting	Type of Tow bar	<b>Tow bar fixed</b>
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining fabrics</b>	
Type of climate control	<b>Autom climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>225/60/17/99 H LightMetal</b>			
Summer tyres:	Fr.L.	<b>Hankook: 6 mm</b>	Fr.R.	<b>Hankook: 6 mm</b>
	Re.L.	<b>Hankook: 5 mm</b>	Re.R.	<b>Hankook: 5 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------

Total cost ex VAT	643,94
Wing R L, Scratch(es), LI - Repair and paint (complete)	308,20



Bumper corner R L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Wing F R, Scratch(es), LI - Repair and paint (complete)	220,18
---	--------



Tailgate, Scratch(es), Acceptable	0,00
-----------------------------------	------

*No pictures to display*

Alloy rim R R, Scratch(es), Acceptable	0,00
--	------

*No pictures to display*

Wing F R, Scratch(es), It - Spot repair	115,56
---	--------



Windscreen, Repaired, Acceptable	0,00
----------------------------------	------

*No pictures to display*