


OPEL Zafira: 1FCY746

Vinnumber:	W0LPD9EM2D2083457	Versionname:	ZAFIRA TOURER ecoFL.Enjoy Act.S/S 130PK
First Registrationdate:	28/05/2013	Fiscalpower:	
Expertise Mileage:	176489	Power Kw:	96
Bodytype:		Body color	Silver
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	3716
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		

Options

Radio CD		Central consol F
GPS storage	SD	Luggage cover
GPS storage		Front parking sensors
Windows electric F		Rear parking sensors
Cruise Control		
Steering wheel multifunctional		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Manual climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/50/17/94 W Steel				
Summer tyres:	Fr.L.	Pirelli: 4,5 mm	Fr.R.	Pirelli: 4,5 mm
	Re.L.	Continental: 5,5 mm	Re.R.	Continental: 5,5 mm





















Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			1423,30
Wing R L, Scratch(es), Acceptable			0,00

No pictures to display

Door R R, Scratch(es), LI - Repair and paint (complete)	318,35
---	---------------



		Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete)	115,56
		Interior, Stain, Acceptable	0,00
		Wheel cover R R, Scratch(es), Acceptable	0,00
No pictures to display			
Wing F L, Scratch(es), Acceptable			0,00
No pictures to display			
Wheel cover F L, Scratch(es), Acceptable			0,00
No pictures to display			
Wheel cover F R, Scratch(es), Acceptable			0,00
No pictures to display			
Front bumper, Scratch(es), LI - Repair and paint (complete)			211,80
			
			
Door R L, Scratch(es), LI - Repair and paint (complete)			318,35
			
			
Tailgate, Scratch(es), LI - Repair and paint (complete)			301,68
			
Door frame R R, Bump(s) and scratch(es), It - Spot repair			115,56
			
Bumper spoiler F, Strained , E - Replace			42,00

