



**MERCEDES CLA: 1HBT939**

Vinnnumber:	<b>WDD1173011N104326</b>	Versionname:	<b>CLA BER 200 CDI 136PK</b>
First Registrationdate:	<b>13/06/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>98455</b>	Power Kw:	<b>100</b>
Bodytype:	<b>Berline</b>	Body color:	<b>.</b>
Gearbox:	<b>MAN 6 VIT</b>	Body color:	<b>Grey</b>
Transmission:	<b>Front</b>	Paint type:	<b>Metalic</b>
Fueltype:	<b>Diesel</b>	Rims summer:	<b>Aluminium</b>
Maintenance:	<b>OK</b>	Oil level:	<b>OK</b>
Maintenance:	<b>A1 DANS 226 JOURS</b>	Parking lot:	<b>3824</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>4</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>1</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F
GPS storage	<b>HD</b>	Front parking sensors
GPS storage		Rear parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining leather</b>	
Type of climate control	<b>Autom climate control</b>	
Level control		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>205/55/16/91 V LightMetal</b>			
Summer tyres:	Fr.L.	<b>Bridgestone: 6 mm</b>	Fr.R.	<b>Bridgestone: 6 mm</b>
	Re.L.	<b>Continental: 7 mm</b>	Re.R.	<b>Continental: 7 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

<b>Total cost ex VAT</b>	<b>1456,96</b>
--------------------------	----------------

<b>Door F L, Scratch(es), Acceptable</b>	<b>0,00</b>
--	-------------



<b>Wing F R, Scratch(es), Acceptable</b>	<b>0,00</b>
--	-------------



Front bumper, Bump(s) and scratch(es), Le - Replace and paint	862,80
---	--------



Bumper R, Scratch(es), LI - Repair and paint (complete)	254,16
---	--------



Wing R R, Bump(s), Acceptable	0,00
-------------------------------	------



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Certificate Of Conformity, Missing, E - Replace	150,00
---	--------



Door R L, Bump(s) and scratch(es), Acceptable	0,00
---	------



Seat cover F L, Worn, P - Check	0,00
---------------------------------	------



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------

